

Oil Field Environmental Incident Summary

Incident: 20150210092653

Date/Time of Notice: 02/10/2015 09:26

Responsible Party: OXY USA INC.

Well Operator: OXY USA INC.

Well Name: CABERNET SWD 1

Field Name: CABERNET

Well File #: 90174

Date Incident: 2/9/2015

Time Incident: 09:30

Facility ID Number:

County: DUNN

Twp: 144

Rng: 97

Sec: 34

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.8 Mile

Distance Nearest Water Well: 0.8 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	20	Barrels	20	Barrels	20	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/10/2015

Clean Up Concluded: 3/10/2015

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

A block valve was installed to isolate the leak, a vac truck was immediately dispatched to suck out the line and recover all standing liquids

Wastes Disposal Location: R360, Chimney Butte

Agencies Involved:

Updates

Date: 2/10/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.